



## Report & Claim Form

TO: Linda		Claim No: 238	
FROM: Olga		Date: 26.02.2012	
		Claim: Connector, 3-Way	
Dealer name: XXXXXX			
Contact person: Olga	Tel:XXXXX		Fax: XXXXXX
Unit Model: FD		Part No: 32512607	
Serial No: 110234945		Engine No: 996743	

**Failure description:**

Among 3-way connectors delivered 2 connectors with no holes for brake sensor mounting were found.

For your information please see picture. # 3121.

**Please replace the 3-way connectors.**

**Answer:**

Warranty Claim Only

Part Description	Part Number	QTY
Connector, 3-way	32512607	2

Note: Please complete detailed information for claim process. Some claim processes require other proof documentation such as pictures. The warranted parts that are being replaced must be returned if requested from the supplier.